

Training Guide
Dishwasher Hose Clamp
Replacement
Model: MDT24H3AST



Revision 1

Date: 4/9/2020

Page 1 of 3


Issue: MDT24H3AST model dishwashers have one time use hose clamps connecting parts.

Instructions: Follow guide for correct replacement clamps when ordering service parts.

Replacement Clamp Part #'s and Sizes:

6760595: 3/8 – 7/8 **6712595:** 1/2 – 1-1/4 **6720595:** 3/4 – 1-3/4 **6736595:** 1-3/4 – 2-3/4

Water Valve (17476000001140) requires a **6760595** clamp.



Wash motor (17476000A02374) requires a **6720595** clamp on the outlet side, and a **6736595** clamp on the inlet side.



Training Guide
Dishwasher Hose Clamp
Replacement
Model: MDT24H3AST





Revision 1

Date: 4/9/2020

Page 2 of 3

Sump (12176000025590) requires a 6712595 clamp, a 6720595 clamp, and a 6736595 clamp.



Air Breather (17476000001636) requires two 6712595 clamps, and two 6760595 clamps.



Training Guide
Dishwasher Hose Clamp
Replacement
Model: MDT24H3AST




Revision 1

Date: 4/9/2020

Page 3 of 3

Drain hoses (1267600000954 & 1267600000955) require four **6712595** clamps.



Fill hoses (1267600000621 & 1267600000179) require four **6760595** clamps.

